Technical assessment report

SAMPLE ONLY / FICTIONAL CCTV FAULT SCENARIO / REF: EC-SAMPLE-001

Reported issue

A business reports that several CCTV cameras stopped displaying images following a thunderstorm. The purpose of the assessment is to identify the fault and recommend corrective action.

Inspection scope

Check recorder status, camera power supplies, protective devices, cable terminations and video transmission paths. Isolate electrical equipment safely before inspection.

Illustrative findings

Two camera power supplies show no output in this example. Recorder operation and remaining camera feeds are normal. The underlying cause of power supply failure has not been established; storm-related surge damage is a possibility, not a confirmed conclusion.

Recommended corrective action

Replace failed power supplies with correctly rated units after approval; inspect affected cable paths and suitable surge protection. Test each camera feed and recording function.

Commissioning and acceptance

Record supply output, live image, recording playback and remote access where applicable. Document remaining defects and obtain customer sign-off.

Report limitations

This is a demonstration of report format, not an actual inspection or insurance claim. Actual findings require an on-site assessment, supporting measurements and photographs.

Connecting technology is easy. Sustaining service is what sets us apart.

010 634 4624 | info@earthconnectsa.co.za | www.earthconnectsa.co.za
Fourways Office Park, Cnr Roos & Granite, Fourways, Johannesburg