TRUE NORTH CONSTRUCTION AND PROJECTS

Building Today • For a Stronger Tomorrow

PROJECT PORTFOLIO

Selected Work & Site Activity



FEATURED SITE RECORD	STATUS
Exterior boundary-wall finishing and detail work	In progress when photographed
PHOTO DATE	**COMPANY**
17 November 2026	TRUE NORTH CONSTRUCTION AND PROJECTS

A developing visual record of the company's construction and finishing work. Project information is limited to details confirmed for this portfolio; further site records can be added as work progresses and is completed.

Company Overview

TRUE NORTH CONSTRUCTION AND PROJECTS is a South African construction business serving customers through on-site construction and property-improvement work. The company travels to client sites to assess work, discuss requirements and prepare quotations.

Registration number	2026 / 870823 / 07
Telephone	075 280 88 36
Email	truenorthconstructionandprojec@gmail.com
Business address	2475 N Section, Johannesburg, Lenasia, Thembelihle 1827

Core Service Areas

• Building and bricklaying	• Renovations and extensions
• Tiling	• Painting and finishing
• General construction work	• Project coordination

Our Working Approach

1. Site visit — We visit the customer's site to understand the work required.

2. Scope and quotation — The work requirements, materials and quotation are discussed before work starts.

3. Site work — Work is carried out at the agreed site and according to the agreed scope.

4. Review and handover — The completed work is reviewed with the customer before handover.

Service area: Lenasia, Thembelihle, Johannesburg and surrounding areas, subject to project requirements and availability.

Featured Project Record

Exterior Boundary-Wall Finishing & Detail Work

Photo date	17 November 2026	**Recorded status**	In progress
Work type	Exterior wall finishing / detail work	**Location**	Not stated in this portfolio

The photographs supplied for this portfolio show site activity along an exterior boundary wall with decorative wall details and a metal entrance gate. A worker is shown carrying out finishing and detail work beside the wall and gate. The images record the work while it was still in progress.

Work visible in the photographs

- Finishing and touch-up activity on an exterior boundary wall.
- Decorative details on the wall and the area beside the entrance gate.
- On-site work activity recorded during the day.





Photo record: overall view of the boundary wall and a closer view of the wall finish.

Portfolio note: No client name, site address, contract value or completion date has been included because these details were not supplied. This entry should be updated with the final completion photographs and confirmed project details when the work is finished.

Site Photograph Gallery

Additional photographs from the same site record, showing close-up finishing activity and the wall-and-gate area.



Close-up view of the exterior wall and decorative detail.



Further view of the boundary wall and entrance-gate area.



Worker carrying out finishing activity beside the gate.



On-site detail work recorded during the project.

Contact TRUE NORTH

Telephone	075 280 88 36
Email	truenorthconstructionandprojec@gmail.com
Registration number	2026 / 870823 / 07

We travel to customer sites for construction and property-improvement work. Contact us to discuss your project and arrange a site visit or quotation.

Building Today • For a Stronger Tomorrow